

## Quick change angle adapter "Quick" (627242000)

- Quick and comfortable fixing of angle adapter without tools
- Quick spindle for fixing the quick change angle adapter 6.27240 and bit holder 6.27241
- Magnetic bit holder with 1/4" (6.35 mm) hexagonal shank
- Suitable for clockwise and anti-clockwise rotation
- Suitable for cordless machines up to a maximum of 110 Nm
- Suitable for Metabo BS 14,4 LT Quick (up to year of construction 01/2013), BS 18 LTX Quick, BS 18 LTX BL Quick, BE 1300 Quick, BE 75 Quick

[Link to Product](#)

### Illustration



Product may differ from Image