



Heavy-duty magnets with on-off switch for easy and safe positioning and removal. The essential time-saving tool for metal layout and fabrication. Turn magnet Off or at the mid-point when setting up, turn On when in final position.

Key Features

- On-off switch allows fast and safe positioning and removal
- Turn magnet Off or at the mid-point when setting up, turn On when in final position
- Ideal for flat, round and square steel profiles
- Easy to clean, simply turn off and wipe



Part No.	Description	Unit
WC-01885	Promax MG22 110x95x25mm 90/45°, max pull force approx 35-40kg*	Each
WC-01886	Promax MG26 150x130x35mm 90°, 45° & 60/30° Multi-Angle, max pull force approx 65-70kg*	Each

